



January 2009



Sun	Mon	Tue	Wed	Thu		Fri	Sat
check weekly: (1) of chloring in chloring with wastewater?,	For sanitary treatment plants (STP), check weekly: (1) compressor, (2) chlorine in chlorinator & in contact with wastewater?, (3) foul odors from discharge, is discharge cloudy?		Check Air Permit. Keep paint and solvent usage records if required.	1 New Year's Day	2	STP 🗀	3
4	5	6	7	Rpt.Workshop Baton Rouge (225) 219-3248	9	STP	10
11	12	Hazardous Waste Rpt. Workshop Lake Charles (337) 491-2688	14 Haz. Waste Rpt. Workshops-Alex. & Shrev.(318) 676-7811 UST Training-Baton Rouge, 1-5 pm (225) 219-3805	15 ** Hazardous Waste Rpt. Workshop West Monroe (318) 397-6100	16	STP	17
18	19 Martin L. King, Jr. Day	20	21	22	23	STP 🔲	24
25 Check water discharge permit: daily visual monitoring for wastewater oil sheen required? Stormwater plans require annual self-inspection.	26	27	28 ** Annual; Semi-annual; and Quarterly Discharge Monitor Report Due	29	30	STP 🗀	31 Questions? Call: 1-800-259-2890

^{**}Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)**



February 2009



Sun	Mon	Tue	Wed	Thu	Fri	Sat
check weekly: (1) chlorine in chlorin	ator & in contact , (3) foul odors from	3	4 UST Training W. Monroe 8 am-12 pm (225) 219-3805	5	6 STP	7
8	9	10	11	12	13 STP	14
15 **	16	17	18	19 SWAT Training Thibodaux 8:30 am-12:30 pm (225) 219-3720	20 STP 🗀	21
Check water discharge permit: daily visual monitoring for wastewater oil sheen required? Stormwater plans require annual self-inspection.	23	24 Mardi Gras	25	26	27 STP Check Air Permit. Keep paint and solvent usage records if required.	28 ** Questions? Call: 1-800-259-2890

^{**}Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)**



March 2009



Sun	Mon	Tue	Wed	Thu	Fri	Sat
1 Hazardous Waste Annual Report; Tier II Report Due	weekly: (1) compres	ant plants (STP), check ssor, (2) chlorine in stact with wastewater?, (3) charge, is discharge cloudy?	4 Check Air Permit. Keep paint and solvent usage records if required.	5	6 STP	7
8 Daylight Saving Time Begins	9	10	UST Training Metairie 1 pm—5 pm (225) 219-3805	12	13 STP [14
15 **	16	17	18	19	20 STP [21
22	23	24	2009 La. Solid To register, go to		27 Iference, Lafayette, La.	28 **
29	30	31 Toxic El in ERIC; Criteria El in ERIC Due	Check water discharge permit: daily visual monitoring for wastewater oil sheen required? Stormwater plans require annual self-inspection.		STP [Questions? Call: 1-800-259-2890

^{**}Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)**



April 2009



Sun	Mon	Tue	Wed	Thu	Fri	Sat
For sanitary treatment plants (STP), check weekly: (1) compressor, (2) chlorine in chlorinator & in contact with wastewater?, (3) foul odors from discharge, is discharge cloudy?		Questions? Call: 1-800-259-2890	1	2	3 STP □	4
5	6	7	8 UST Training Shreveport 8 am-12 pm (225) 219-3805	9	STP	11
12 Easter	13	14	15 ** Federal Income Tax Due	16	17 STP □	18
19 Earth Day	20	21	22	23 SWAT Training Crowley 8:30-12:30 pm (225) 219-3720	24 STP □	25
26	27	28 ** Quarterly Discharge Monitoring Report Due	29	Asbestos & Lead Workshop - DEQ Headquarters Baton Rouge 8:00 am-1:00 pm	Check Air Permit. Keep paint and solvent usage records if required.	Check water discharge permit: daily visual monitoring for wastewater oil sheen required? Stormwater plans require annual self-inspection.

^{**}Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)**



May 2009



Sun	Mon	Tue	Wed	Thu	Fri	Sat
Check water discharge permit: daily visual monitoring for wastewater oil sheen required? Stormwater plans require annual self-inspection.	OZONE SI	EASON BEGINS (N	May through Septembe	e <mark>r)</mark>	1 STP □	2
3	4	5	6	7	8 STP 🗆	9
10	11	12	UST Training Crowley 8 am-12 pm (225) 219-3805	14	15 ** STP La. State Income Tax Due	16
17	18	19	20	21	22 STP	23
24	25 Memorial Day	26	27	28 **	29 STP 🗀	30
31	(1) compressor, (2	ment plants (STP), one control of the control of th		Check Air Permit. Keep paint and solvent usage records if required.	Questions? Call: 1-800-259-2890	

^{**}Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)**



June 2009



Sun	Mon	Tue	Wed	Thu	Fri	Sat
Check Air Permit. Keep paint and solvent usage records if required.	1	2	3	4	5 STP	6
7	8	9	UST Training Baton Rouge 1 pm—5 pm (225) 219-3805	11	12 STP 🗀	13
14	15 **	16	UST Training Alexandria 8 am-12 pm (225) 219-3805	18 SWAT Training Ruston 8 am-12 pm (225) 219-3720	19 STP 🗀	20
21	22	23	24	25	26 STP	27
28 **	29	30	For sanitary treatments check weekly: (1) of the chlorine in chlorina with wastewater?, discharge, is discharge.	compressor, (2) ator & in contact (3) foul odors from	Check water discharge permit: daily visual monitoring for wastewater oil sheen required? Stormwater plans require annual self-inspection.	Questions? Call: 1-800-259-2890

^{**}Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)**



July 2009



Small Business Reporting Calendar
DEQ permit maintenance fee invoicing begins. Pay by due date to keep active.

Sun	Mon	Tue	Wed	Thu		Fri	Sat
check weekly: chlorine in chlowith wastewat	eatment plants (STP), (1) compressor, (2) orinator & in contact er?, (3) foul odors from lischarge cloudy?	Questions? Call: 1-800-259-2890	1 Form R or A (TRI); Minor Source Air Toxic Rpts; Perc Form Due	2	3	STP 🗀	4 Independence Day
5	6	7	UST Training Metairie 8 am-12 pm (225) 219-3805	9	10	STP	11
12	13	14	15 **	16	17	STP 🗀	18
19	20	21	22	23	24	STP	25 Check Air Permit. Keep paint and solvent usage records if required.
26	27	28 ** Semi-annual & Quarterly Discharge Monitoring Report Due	29	30	31	STP 🗀	Check water discharge permit: daily visual monitoring for waste- water oil sheen re- quired? Stormwater plans require annual self-inspection.

^{**}Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)**



August 2009



Sun	Mon	Tue	Wed	Thu	Fri		Sat
			Check Air Permit. Keep paint and solvent usage records if required.			STP 🗀	Ann. Rpt. For Generators, Processors, Disposers of Solid Waste Due
2	3	4	5	6	7	STP	8
9	10	11	UST Training Shreveport 8 am-12 pm (225) 219-3805	13	14	STP 🗀	15 **
16	17	18	19	SWAT Training Alexandria 8 am-12 pm (225) 219-3720	21	STP	22
23	24	25	26	27	28 **	STP	29
30	31	For sanitary tre compressor, (2 wastewater?, (cloudy?	Check water of permit: daily vice monitoring for water oil shee quired? Storm plans require self-inspection	risual r waste- en re- nwater annual	Questions? Call: 1-800-259-2890		

^{**}Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)**



September 2009



Sun	Mon	Tue	Wed	Thu	Fri	Sat
For sanitary treatment plants (STP), check weekly: (1) compressor, (2) chlorine in chlorinator & in contact with wastewater?, (3) foul odors from discharge, is discharge cloudy?		1 Labor Day	UST Training W. Monroe 8 am-12 pm (225) 219-3805	3	4 STP □	5
6	7	8	9	10	11 STP □	12
13	14	15 **	UST Training Baton Rouge 1 pm—5 pm (225) 219-3805	17	18 STP □	19
20	21	22	23	24	25 STP	26
27	28 **	29	30 Stage II Certificate expires Ozone Season Ends	Check Air Permit. Keep paint and solvent usage records if required.	Check water discharge permit: daily visual monitoring for waste- water oil sheen re- quired? Stormwater plans require annual self-inspection.	Questions? Call: 1-800-259-2890

^{**}Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)**



October 2009



Sun	Mon	Tue	Wed	Thu	I	Fri	Sat
For sanitary treatments check weekly: (1) of the chlorine in chlorina with wastewater?, discharge, is discharge.	compressor, (2) ator & in contact (3) foul odors fron	1	Check Air Permit. Keep paint and solvent usage records if required.	1	2	STP 🗀	3
4	5	6	7	8	9	STP 🗀	10
11	12	13	14 UST Training Crowley 8 am-12 pm (225) 219-3805	15 **	16	STP 🗀	17
18	19	20	21	22 SWAT Training St. Tammany 8:30 am-12:30 pm (225) 219-3720	23	STP 🗀	24
25 Check water discharge permit: daily visual monitoring for wastewater oil sheen required? Stormwater plans require annual self-inspection.	26	27	28 ** Quarterly Discharge Monitoring Report Due	29	30	STP 🗀	31 Questions? Call: 1-800-259-2890

^{**}Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)**



November 2009



Sun	Mon	Tue	Wed	Thu	ı	Fri	Sat
1 UST Worker Certification Renewal Due Daylight Saving Time Ends	2	3	4	5	6	STP 🗀	7
8	9	10	UST Training Alexandria 8 am-12 pm (225) 219-3805	12	13	STP 🗀	14
15 **	16	17	18	19	20	STP 🗀	21
22	23	24	25	26	27	STP 🗀	28 **
				Thanksgiving Day			
29 Check water discharge permit: daily visual monitoring for wastewater oil sheen required? Stormwater plans require annual self-inspection.		Check Air Permit. Keep paint and solvent usage records if required.	For sanitary treatments check weekly: (1) of chlorine in chlorina with wastewater?, discharge, is discharge.			Questions? Call: 1-800-259-2890	

^{**}Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)**



December 2009



Sun	Mon	Tue	Wed	Thu	Fri	Sat
For sanitary treatment plants (STP), check weekly: (1) compressor, (2) chlorine in chlorinator & in contact with wastewater?, (3) foul odors from discharge, is discharge cloudy?		1	2	3	4 STP □	5
6	7	8	9	SWAT Training Baton Rouge 8 am-12 pm (225) 219-3720	11 STP	12
13	14	15 **	16	17	18 STP	19
20	21	22	23	24	25 STP 🗆	26
					Christmas Day	
27 Check water discharge permit: daily visual moni-	28 **	29	30	31 UST Worker Certification expires	Check Air Permit. Keep paint and	Questions? Call:
oring for wastewater oil heen required? Storm-vater plans require anual self-inspection.				Lead Contractor Letter of Approval expires	solvent usage records if required.	1-800-259-2890

^{**}Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)**



Small Business/Small Community Assistance Program Contacts

Hotline: 1-800-259-2890 (in-state only) E-Mail: SBAP@la.gov

Serving Small Businesses and the Environment

Engineer Manager	Regional Office	Phone No.	Fax No.	E-Mail
Yanfu Zhao, P.E.	Baton Rouge Hdqtrs.	225-219-3258	225-219-3971	yanfu.zhao@la.gov
Engineer 5				_
Jennifer Pelloat, P.E.	Baton Rouge Hdqtrs.	225-219-0879	225-219-3971	jennifer.pelloat@la.gov
ES Supervisor				_
Jason Dewitt	Kisatchie/Northeast	318-487-5528	318-487-5927	jason.dewitt@la.gov
Admin. Assist. 4				
Patricia Rogers	Baton Rouge Hdqtrs.	225-219-3969	225-219-3971	patricia.rogers@la.gov
SBSCAP Engineers				
Jada Lewis	Capital	225-219-3260	225-219-3971	jada.lewis@la.gov
Larry Lashley	Northwest/Northeast	318-676-5088	318-676-7573	larry.lashley@la.gov
Mike Savoy	Acadiana	337-262-5591	337-262-5593	john.savoy@la.gov
Kurt Wilson	Southeast/Bayou Lafourche	504-736-7767	504-736-7702	kurt.wilson@la.gov
Markle Farber	Southwest	337-491-2804	337-491-2682	markle.farber@la.gov
My Trinh	Southeast (Harahan)	504-736-7768	504-736-7702	my.trinh@la.gov
Environmental Scientists				
Beth Kimball	Southeast (Mandeville)	985-624-4170	985-624-4447	beth.kimball@la.gov
Ryan Brignac	Acadiana	337-262-1566	337-262-5593	ryan.brignac@la.gov
Katrina Daigrepoint	Northeast	318-484-2120	318-487-5927	katrina.daigrepont@la.gov
Bobby Kingham	Southwest	337-491-2721	337-491-2682	robert.kingham@la.gov
Ned Richard	Northwest	337-676-7580	318-676-7573	ned.richard@la.gov
OSEC/BCOD Administrator				_
Bijan Sharafkhani	Baton Rouge Hdqtrs.	225-219-3956	225-219-3971	_bijan.sharafkhani@la.gov
OSEC/Ombudsman				
Lenny Young	Baton Rouge Hdqtrs.	225-219-0860	225-219-3971	lenny.young@la.gov